

CONFIDENTIAL

25X1A

Gentlemen:

Enclosed are five (5) copies of the December 15, 1967 vibration report.

This report indicates that the vibrations found at the first floor are similar to those found at the second floor in the October test.

These findings lead to our recommendation that the piece of equipment be installed at the first floor level because the cost of a vibration isolation device will be much less at the first floor than the second floor.

25X1A

Please let us know your location decision so we may proceed to the next phase which should be a meeting with foundation consultant and ourselves.

25X1A

Very truly yours,



25X1A

Declass Review by NIMA/DOD

CONFIDENTIAL